



■ Post-Repair Care Instructions

■ Paint Care

- ✓ No washing for 48–72 hrs.
- ✓ Please note, clear coat can take up to 30 days to fully cure.
- ✓ No waxing/polishing for 30 days.
- ✓ Hand wash only (mild soap/soft cloth).

■ Driving & Handling

- ✓ Drive gently after repair.
- ✓ Paint odor is normal & fades.

■ Inspect Vehicle

- ✓ Check for imperfections in good light.
- ✓ Report issues immediately.

■ Weather Protection

- ✓ Avoid trees & droppings.
- ✓ Garage/shade when possible.

■ Adhesives & Decals

- ✓ No high-pressure washes 30 days.
- ✓ No scrapers/sharp tools.

■■ Safety Systems

- ✓ Drive carefully if sensors/alignment fixed.
- ✓ Return if warning lights stay on.

■ Follow-Up

- ✓ Keep receipt & warranty.
- ✓ Ask if 2–4 week check is needed.

Thank you for trusting Perfection Body Shop & Auto Repair of Naples!